



Cracking around the edges of a feather-edge repair.

### **CAUSE**

- Too much or poor quality thinner or reducer.
- Improper substrate preparation brought about by using coarse papers on feather edges with resultant attack by solvents from the following paint coatings.
- 'Piling-on' in heavy wet coats.
- Effect of an old finish or previous repair.
- Poor shop temperature (too cold).
- Fanning with air to dry.